

## State Water Resources Control Board

October 12, 2016

(Via email and Certified Mail)  
**CERTIFIED MAIL**  
**NO. 7015 1520 0001 8019 7221**

Mr. Bryan Basile  
Transportation Lead Mechanic  
Murrieta Valley Unified School District  
41870 McAlby Court  
Murrieta, California 92562  
[josborn@tvusd.k12.ca.us](mailto:josborn@tvusd.k12.ca.us)

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS  
LOCATED AT MURRIETA VALLEY UNIFIED SCHOOL DISTRICT,  
41870 MCALBY COURT, MURRIETA**

Dear Mr. Basile:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on September 21, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	<b>Failure to Maintain Overfill Prevention</b> – The automatic tank gauge for the unleaded tank did not get tested during the last monitoring certification on April 13, 2016, and there is no fill tube shut-off valve as another means of overfill prevention.	Unleaded 3	September 21, 2016	Ongoing	H&SC 25291(c); 23 CCR 2635(b)(2)
2	<b>Failure to Maintain Release Response Plan</b> – This document must be updated with a current employee for the point of contact.	All	September 21, 2016	Ongoing	23 CCR 2632(d)(2)(B)

No.	Violation	Tank	Start Date	Stop Date	Regulation
3	<b>Failure to Maintain Facility and Tank Information (B Forms)</b> – Diesel tank one needs a tank ID listed on the tank information form.	Diesel 1	September 21, 2016	Ongoing	23 CCR 2711(a)
4	<b>Failure to Maintain Financial Responsibility</b> – The insurance plan is valid; however a copy of the policy was not available at the time of inspection.	All	September 21, 2016	Ongoing	23 CCR 2711(a)(11)
5	<b>Failure to Monitor Product Piping</b> – The sensor in the Diesel 2 piping sump is not in a vertical position at the lowest point in the sump.	Diesel 2	September 21, 2016	Ongoing	23 CCR 2630(d)
6	<b>Failure to Monitor Product Piping</b> – The sensors in all of the under dispenser containment (UDC) devices are not at the lowest point in the UDCs; they must be positioned along the outer tray of the UDC where it drops to the lowest point.	1,2,3	September 21, 2016	Ongoing	23 CCR 2630(d)

**You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Riverside County Department of Environmental Health within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.**

Please send all compliance documentation to the following:

**State Water Board**

Ms. Rebecca Green  
UST Enforcement Unit  
Office of Enforcement  
State Water Resources Control Board  
1001 I Street, 16<sup>th</sup> Floor  
Sacramento, California 95814  
[rebecca.green@waterboards.ca.gov](mailto:rebecca.green@waterboards.ca.gov)

**Local CUPA**

Mr. Jonathan Lance  
Hazardous Materials Management Specialist  
Department of Environmental Health  
County of Riverside  
800 Sanderson Avenue, Suite 102  
Hemet, California 92545  
[jonlance@rivcocha.org](mailto:jonlance@rivcocha.org)

Pursuant ant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at [amantha.henkel@waterboards.ca.gov](mailto:amantha.henkel@waterboards.ca.gov).

Sincerely,



Amantha Henkel  
Senior Environmental Scientist  
UST Enforcement Unit  
**Office of Enforcement**

cc: (via email only)

Mr. Jeff Johnson  
Program Chief II  
Riverside County Department of  
Environmental Health  
[jeffjohnson@rivcocha.org](mailto:jeffjohnson@rivcocha.org)

Mr. Uche Okwuokei  
Hazardous Materials Management Specialist  
Riverside County Department of  
Environmental Health  
[uokwuokei@rivcogha.org](mailto:uokwuokei@rivcogha.org)

Ms. Tamara McDaniel  
Transportation Department Secretary  
Murrieta Valley Unified School District  
[tmcdaniel@murrieta.k12.ca.us](mailto:tmcdaniel@murrieta.k12.ca.us)